LARGE DIESEL ENGINE SERVICE MANUAL
(1st Edition)

CONTENTS

Allis-Chalmers
649, 670 2
David Brown (Case)
165001/2, 220001/2, 220101 20
J.I. Case
188D, 264BD, 336BD, 401BD, 451BD, 451BDT 39
John Deere
3164D, 3179D, 4219D, 4239D, 4239T, 4276D, 4276T, 6329D, 6359D, 6359T, 6404D, 6404T, 6404A, 6414D, 6414T, 6466D, 6466T, 6466A 63
Ford
SSD-327, YSD-635, SSD-437, SSD-655, SSD-681 89
International Harvester
D-179, D-206, D-239, D-246, D-268, D310, D-358 106
D-312, D-360, D-414, DT-414, DT-414B, D-436, DT-436, DT-436B, D-466, DT-466, DT466B, DTI-466B 121
Lister
HR3, HRW3, HR4, HRW4, HR6, HRW6, HRS6, HRSW6 137
Lombardini
834, L54 148
Perkins
A4.203, A4.236, A4.318, A6.354, AT6.354 154

Some illustrations reproduced by permission of Deere & Company
Copyright Deere & Company

Front cover photo courtesy of Lister-Petter.

CLYMER®
PROSERIES

P.O. Box 12901 ■ Overland Park, KS 66282-2901

Copyright 1983 by Clymer. Printed in the United States of America

Phone: 800-262-1954 Fax: 800-633-6219
www.clymer.com
February, 2007

All rights reserved. Reproduction or use of editorial or pictorial content, in any manner, without express permission is prohibited. No patent liability is assumed with respect to the use of the information contained herein. While every precaution has been taken in the preparation of this book, the publisher assumes no responsibility for errors or omissions. Neither is any liability assumed for damages resulting from use of the information contained herein. Publication of the servicing information in this manual does not imply approval of the manufacturers of the products covered.

All instructions and diagrams have been checked for accuracy and ease of application; however, success and safety in working with tools depend to a great extent upon individual accuracy, skill and caution. For this reason the publishers are not able to guarantee the result of any procedure contained herein, nor can they assume responsibility for any damage to property or injury to persons occasioned from the procedures. Persons engaging in the procedures do so entirely at their own risk.